

SEARCH RESULTS

VIN: 1J8GLN8702W290074  
Year: 2002  
Vehicle: JEEP LIBERTY SPORT 4X4 SPORT  
UTILITY 4-DR




**Questions**  
Please contact the Chrysler Group Recall Assistance Center at 1-800-853-1403

**Do you Qualify for Recall Reimbursement?**  
If you've had a recall on your vehicle and have incurred recall-related costs you'll need to start the reimbursement request process (all on a case-by-case basis).

Results Last Updated: August 04, 2015

Safety Recalls (What is a Safety Recall? [Learn More](#))

[Submit Reimbursement](#)

Status	Chrysler Recall #	NHTSA Recall #	Recall Date	Safety Defect/Non Compliance Description and Safety Risk	Repair Description	Recall Status
<div> Incomplete</div>	M35	12V-527	November 07, 2012	THE AIRBAG SYSTEM OCCUPANT RESTRAINT CONTROL (ORC) MODULE MAY EXPERIENCE A FRONT AIRBAG AND/OR SEATBELT PRETENSIONER INADVERTENT DEPLOYMENT AN INADVERTENT DEPLOYMENT WHILE DRIVING COULD DISTRACT THE DRIVER AND CAUSE A CRASH WITHOUT WARNING.	ALL INVOLVED VEHICLES MUST HAVE A JUMPER HARNESS WITH AN IN-LINE DIODE FILTER CIRCUIT INSTALLED.	INCOMPLETE BUT REPAIR PARTS ARE AVAILABLE
<div> Incomplete</div>	N46	13V-252	June 18, 2013	THE FUEL TANK ON YOUR VEHICLE HAS A SMALL CHANCE OF EXPERIENCING A FUEL LEAK DURING CERTAIN TYPES OF REAR END COLLISIONS. FUEL LEAKAGE IN THE PRESENCE OF AN IGNITION SOURCE CAN RESULT IN AN UNDERBODY FIRE.	CHRYSLER INTENDS TO INSPECT YOUR VEHICLE AND INSTALL AN ORIGINAL EQUIPMENT MANUFACTURER (OEM) TRAILER HITCH WHERE APPROPRIATE, FREE OF CHARGE (PARTS AND LABOR) TO BETTER MANAGE CRASH FORCES IN LOW-SPEED IMPACTS.	INCOMPLETE BUT REPAIR PARTS ARE AVAILABLE
<div> Incomplete</div>	R06	15V-046	January 27, 2015	THE AIRBAG SYSTEM OCCUPANT RESTRAINT CONTROL (ORC) MODULE MAY EXPERIENCE A FRONT AIRBAG AND/OR SEATBELT PRETENSIONER INADVERTENT DEPLOYMENT. AN INADVERTENT AIRBAG DEPLOYMENT WHILE DRIVING COULD DISTRACT THE DRIVER AND CAUSE A CRASH WITHOUT WARNING.	ALL INVOLVED VEHICLES MUST HAVE THE OCCUPANT RESTRAINT CONTROL (ORC) MODULE REPLACED. IF YOUR VEHICLE STILL HAS SAFETY RECALL M35 (12V-527) OR N13 (13V-040) IN THE "OPEN" STATUS, PLEASE SCHEDULE YOUR SERVICE APPOINTMENT WITH A CHRYSLER DEALER TO PERFORM THE REPAIR. IF YOU ALREADY HAD M35 (12V-527) OR N13 (13V-040) COMPLETED, RECALL R06 MUST STILL BE COMPLETED ONCE PARTS BECOME AVAILABLE.	INCOMPLETE BUT REPAIR PARTS ARE NOT AVAILABLE

Viewing 3 of 5 total recalls  
[View More Recalls](#)

Campaigns (What is a Campaign? [Learn More](#))

There are no outstanding campaigns for the above listed VIN

**Disclaimer**  
Notification letters issued prior to 1999 are not available online. Please contact us by email to request a copy.

**Note**  
Acrobat Reader 5.0 or later is required to view documents.  
[Click here for a free download](#)